

A Division of the Angelus Corporation  
 Ph (262) 246-0500 Fax (262) 246-0450 www.picwire.com  
 PO Box 330 Sussex, WI 53089

Approved : *MCS*  
 Distribution : USER

Date : 02/20/14  
 Rev. 1 (05/31/16)  
 Uncontrolled if Printed

**Termination Instructions for PIC RJ45 Shielded Plug P/N 110789**

(for E6A0824, E6A2824, E6A3824 & E6A6824 Ethernet Cables)

Required Tooling :	PIC P/N 110288 Crimp Tool (Sentinel P/N 900007), Heat Gun
Recommended Tooling :	X-acto Knife, Sharp Razor, Wire Cutters, Locking Tab Heat Shield, Eye Loupe / Magnifier

Dimensions in Inches (NOT to Scale)

- 1) Install labels (if applicable). Install ATUM heat shrink (8/2 x 1.375") on cable. Make Cut A @ 1.0" from cable end, through the cable jacket (Fig. 1). Do Not nick or cut into the braids. Remove jacket.
- 2) Fold each pair back, and trim off the center spline as short as possible, using caution to avoid nicking or cutting into the wires (Figs 2a, 2b). Inspect wire insulation to verify insulation integrity.
- 3) Arrange the wires into the desired configuration, and install the wires into the Load Bar (Figs 3a, 3b). If connector orientation is critical, then orient pairs prior to untwisting any pairs. If necessary, longer wires can be trimmed nearly as short as the shortest wire, to allow easier entry into the Load Bar. Position the Load Bar so that the front edge is 0.85" from Cut A (as shown). Trim off the end of the wires at Cut B (0.85" from Cut A, as shown). All wires should be trimmed evenly, and flush with the end of the Load Bar.
- 4) Make Cut C (0.30" from Cut A) through the Jacket (Fig. 4). Do Not nick or cut into wire braids. Score the 0.30" section of Jacket lengthwise and remove the jacket only.
- 5) Bend the connector body strain relief tab down (Fig. 5a) to allow wires / load bar installation. With the load bar positioned at the end of the wires, install the connector body onto the wires / load bar (Fig. 5a). Seat all wires fully into the connector, until the stranded conductors of each wire are visible through the front end of the connector body (Fig. 5b).
- 6) After verifying full insertion, ensure the exposed shield is aligned with the Metal Strain Relief as shown (Fig 6). Crimp the connector using PIC 110288 Crimp Tool.
- 7) Slide up the 1.375" piece of heat shrink to the back of the boot and shrink, ensuring heat is kept away from the latching tab. It may deform and/or melt with too much heat (Fig 7).
- 8) Verify all wires are fully seated per 110789 Inspection Criteria below.




Figure 2a




Figure 2b




Figure 3a (568A shown)

Figure 3b





Figure 5a


Figure 5b (568A shown)



Strain Relief Tab

ALL stranded wires visible

**Inspection Criteria**



ALL wires fully seated

Pin	568A Configuration	568B Configuration
1	White / Green	White / Orange
2	Green	Orange
3	White / Orange	White / Green
4	Blue	Blue
5	White / Blue	White / Blue
6	Orange	Green
7	White / Brown	White / Brown
8	Brown	Brown



Figure 6



Figure 7

Latching Tab